

## CHAPTER 52-03-04 TEST SAMPLES

### Section

52-03-04-01	General Conditions
52-03-04-02	Tests to Verify Continuing Performance
52-03-04-03	Number of Helmets to be Tested
52-03-04-04	Marking of Reference Plane

**52-03-04-01. General conditions.** In order to qualify under this article helmets shall be tested in accordance with all procedures set forth in this article. The tests shall be conducted on helmets as offered for sale.

**General Authority:** NDCC 39-02-03  
**Law Implemented:** NDCC 39-10.2-06

**52-03-04-02. Tests to verify continuing performance.** After a particular make and model has been qualified, further quality control tests or tests to verify continuing satisfactory performance can be accomplished by conducting only the room temperature portion of the tests.

**General Authority:** NDCC 39-02-03  
**Law Implemented:** NDCC 39-10.2-06

**52-03-04-03. Number of helmets to be tested.** Four helmets will be required for qualification testing.

**General Authority:** NDCC 39-02-03  
**Law Implemented:** NDCC 39-10.2-06

**52-03-04-04. Marking of reference plane.** The reference plane shall be marked on the helmet prior to test, and all tests shall be conducted above the reference plane.

**General Authority:** NDCC 39-02-03  
**Law Implemented:** NDCC 39-10.2-06